

D&RGW:Montrose, Colo.
454 : Harms

April 19, 1950
File 28131

12.

Locomotive moved unexpectedly due to leaky throttle; both valve seats were shou- dered and lower seat was steam cut; slots in throttle valve lifting stem were not standard and rigging did not hold valve on seat when in closed position; one injured.


2 photographs.



Accident D&RGW 454 at Montrose,
Colorado, April 19, 1950.

Locomotive standing outside
enginehouse doors with left 4
tender wheel on chain mark, as
it may have been before the
accident.

Harms
File 28131



Accident D&RGW 454 at Montrose,
Colorado, April 19, 1950.

Locomotive standing where found
after accident; blocking chain
lying where found, and Master
Mechanic pointing at marks on
rail.

Harms
File 28131